<b>1</b>	M48	,	• • •

1 Case Number N99 C C C 1	)		stigato   8 9	r ID	?	ice Code ) 0	EPIDE	EPIDEMIOLOGIC INVESTIGATION REPORT		
4 Accident date 9 4 1 0 2 3			initiate 0 1 1 7							
6 Synopsis of Accide college dormitory. around an operatin to melt and smolde	The o	ccupant er over	sat son. The	ome groce heat fro	eries	in thin :	plastic gro	cery l	bags on and	
7 Location Dermitory 1 0			8 City Chap	l		9 State N C				
10a First Product toaster oven  0 2 1 6  11a Trade/Brand name/Model model: TR0400TY1 brand: Black & Decker Mfr.: Black & Decker Mfr., East Joppa Rd., Towson, MD 21204										
10b Second Product plastic bag		1130	)	ľ	de/Brai nown	nd name/	Mode1			
, ,	3 Sex No inj.	9	-	oosition njury		0	15 I <b>njury</b> No injury	diagno	osis 7 1	
16 Body part No injury 9			ondents Safety	Fire I	Dept. 2		stigation to	/pe	19 Time spent 6.0	
20 Attachments Multi	9	21 Cas Newsp	se Sourc	ce	0 5	22 Revi	ewed by 9342	9	750301	
23 Permission to dis CPSC	close n may di					CPSC	may not di	sclose	e my name	
24 Narrative						25 Regi	onal Direct	or rev	ylew date 3-/-95	
					11					
		MFR/	PRVLBR N	No Commen Lexcisions	15 0115	~				
) 				Excisions Firm has further	not req	<sub>lested</sub>				

NOTE:

The information contained in this report was provided by the local responding fire department and the University safety officer. I was never able to reach the owner of the toaster oven involved in the incident.

# PRE-INCIDENT:

This residential fire occurred in one of the university's dormitories. The fire occurred on Oct. 23, 1994 at approximately 4:30 pm. The product involved in the fire was a Black and Decker brand toaster oven. The toaster oven was sitting on a desk. The occupant stated to fire investigator's that she last used the toaster oven around 9:00 am. on the day of the fire. The occupant did not know where the toaster oven had been purchased, but it was new, less than one year old. Prior to the incident the occupant had not experienced any problems with the toaster oven.

The occupant went grocery shopping on the day of the fire and returned to her room around 3:00 pm. She had purchased some groceries and they were bagged in thin plastic grocery bags. When she returned to her room she sat the groceries on and beside the oven. The groceries were left in the bags and the occupant left about 10 minutes later. The occupant did not return to her room until after the fire.

# INCIDENT:

A passerby saw smoke coming from around the occupants window. Authorities were alerted and the fire department was called. When the fire department arrived they found that the toaster oven was operating and the heat from the oven had melted the plastic grocery bags and caused them to smolder. There were no actual flames.

## POST-INCIDENT:

Removal of the bags from around the toaster oven and turning the oven off eliminated the fire. The smoke was removed from the room by the fire department. They did not remove the toaster oven. The damage was minimal and the university's insurance company was not involved. The occupant believes she may have inadvertently turned the toaster oven on as sat the groceries down.

# PRODUCT IDENTIFICATION:

The toaster oven involved in the incident was a Black and Decker model TR0400TY1. No other product information was available as I was never able to speak to the owner. The safety officer for the university, on my behalf, went by the occupant's room and talked to her. He was not able to get any additional product information as the occupant discarded the toaster oven following the incident.

# ATTACHMENTS:

Attachment 1 - Fire Report

	Grid	FD10 016181012	Department N	/ //- //	FZ	)				0	ounty   Exp.	Incident No.
	10-B		rr. Day of W	eek Alarm Time	Time C	12/1	ur. Tim		ne In To	t. Time Ou	)	1 5 76
	INCIDENT	Street Man	nina	Drive	1.1.1.	-1	<u>- 1-</u>		Rm. or Ap	<u> </u>	I INE SERVI	ICE RESPONSE
	ADDRESS OR LOCATION	City Ha	DF1	411			State	/(	21715	J 1919	Personnel	1115
1	OCCUPANT NAME	Last. First	/ IAME	S DORM.	Phone				Muti	lal Aid k one	Engines	1 3
-	OWNER NAME	Last, First	VC	DONAL	Phone				[ ] F	Received	Aerials	
-		Street R	Spial	P.	<u>'                                    </u>				2	iiven	Tankers	
	OV/NER ADDRESS	City HE	PFI	-41	/ /		State		ZIP	ot Apply	Other Vehicles Hazardous Ma	aterials Involved
,		PLEASE PUT	APPROPRIATE	CODE NUMBER IN	BOX FOR	EACH CA	AZ TEGO	RY	2175	17	1 Yes	2 No
l	METHOD OF ALARM FROM PUBLIC		JATION FOUND		losion not d	classified	T	YPE OF AC	TION		REQUIRES CO	MPLETION OF
_	1 Telephone	11 Structure fi 12 Any fire ou	tside a structure	combust 30 Rescue			1	Extinguish	nment	31	No. Incident-r	
	Municipal alarm     system     Private alarm system	has a value	material burning	40 Hazardoi	us condition	n	3	! Rescue i Investigati Remove h		rimary	sr. 10	Other     O
,	4 Radio	14 Trees, brus	h, grass fire (material burn-	50 Service of 60 Good into	ent call		5	Standby Salvage		<i>71</i> 1 1	No. Incident-re Fire ··· Srv.     1 d	
	6 Home dialer 7 Tie-line	ing has no	/alue)	73 Faise ma	lfunction		7	Medical Ai			Is juvenile suspec	
	8 Voice signal: Fire alarm system	17 Outside spi	l, leak with fire	74 False unii 99 Other situ		3	9	Cancelled Water supp	enroute	1	YES 2	NO
	9 Other					1/	ls p	<u></u>	indoned or v	racant?	Yes 2	No
	Fill in this section if	TYPE OF SITUATIO	N FOUND* is 1 fer to coding sh		9 ONLY (14	, Optional	)	1 ~	perty Use	,		
}	Ignition Factor	(ne		of Fire Origin	·	<del></del>			idential It Involved in			400
j	OPERATION	AL DEFICIENCY	10	Bedroom	]	نــ	21	Coe		-	pment	20
Ļ		quipment	20 p	of Material Ignited	í 	4	6	Form of M	laterial Ignite	ed		90
	f Heating Equipment Invo Type of Fuel Used	2	Kerosene LPG Electric	5 Coal	7 Natural 8 Gasoline 9 Other	Gas [	0	PROPERT 1 \$1-99	/ DAMAGE C	LASSIFICAT		ated Value
$\mid$	CONDITION UPON ARRIVAL	MOBILE PROPER		reight road transp	0 Not App	iy Vot Appiy		2 \$100-9 3 \$1,000- 4 \$10,000	9,999 1-24 999		Structu	imated ral Damage
	1 Overheat	11 Automobile 12 Bus	40 1	Pail transport Water transport				5 \$25,000	)-49,999 )-149,999	Dam.	aged	
	2 Smoldering 3 Oper flame 8 Out on arrival	13 All-terrain vehice 14 Motor home	60 1	Air transport leavy equipment		Г	$\neg 1$	8 \$500,00	0-499,999			imated ts Damage
Ļ.		15 Travel trailer 17 Mobile home	70 S 99 C	Special vehicles, co Other mobile prope	ntainers rty types	0	0		000 or more LAR LOSS			200
_		Yr. Make		Model 		St. Lic.	. Numt	oer		Serial Num	ber/VIN	
	Ignition	Yr. Item Toast	er	Make Black +[	Pecker	Model TR	04	:00T	YI	Serial Numb	ber ) 400T	YI
_	NO. OF STORIES Single Story	1 Confined to the o	· ·				_	DETECTO				No. 2
3	Two Stories 3 or 4 5 or 6	2 Confined to part of 3 Confined to room 4 Confined to fire-ro	of room or area of origin ated comp. of or	~	1	Flame [		If Present, 1	Гуре		moke 2	Not Present
6	7 to 10 11 to 20	5 Confined to floor 6 Confined to struct	ure of origin		S	moke 🗀	<u> </u>   L					
8	21 to 50 Over 50 Below Grade  7 Extended beyond structure of origin 9 No damage of this type Water  Power Supply 1 Battery 2 A/C 1 In room of fire: operated								A/C			
		CONSTRUCTION TY	PE SPRINKL	ER PERFORMANC	E		<b>┤</b> :	2 Not in room o	om of fire: of	perated at operate		
	eight [3]	1 Fire resistive 2 Noncombustible 3 Heavy timber	2 Equipm	ent operated ent inservice, did n ent present: fire too	ot operate	operate		4 Not in roo 5 In room: 1	om of fire: di fire too smal ified (Not Ap	d not operate I to operate	ate e	2
	re Origin	4 Ordinary 5 Frame 0 Other	8 No equi 9 Equipm	pment present ent not in service		8	' ]   Fii	re Referred	for Investiga	ition to:	1 Yes 2	No
1	icer in Charge (name, pos VEV/LLE	sition) , FED		aking Report wille					hme		/	
:n	narks:	,					グァ	700	11111	コハナ	17.0	
			DEC	ADTMENT	0001	(	15	010	40	() ()	1218	

DEPARTMENT COPY

2129 1

Oller Dobbens

Ple flor profiles 6 1 795

ACCIDENT INVESTIGATION FEQUEST FORM

Document Number NHC-014	BO toasten o	von	
Date of Incident 10/23/94	Category I.D.	SECT	15/1995
Follow-Up Requested	Razard Analysis		(Section 15)
Type Follow-Up Requested	Telephone Call	Or	On-Site)
Readquarters Contact R. Roun	Mendina		
Assignment Message 00tain -	touston move	for: 8	Mainerum
eighuntion - Comp	ete on-site	mlu	if franteli
ovam is still available	. Obtain fix	e dois	recont.
			•
D(-) to govern	11.11 0.		
Person(s) to Contact O ( happy	HAM FIRE WILL	42Na12	
(3) KDVC	Mr assistem	<del>/</del>	
		· · · · · · · · · · · · · · · · · · ·	C2 - 27.4 (2)
Ruideline		e.	
			Walter transfer to the Control of th
· .			The state of the s
Requested By RR			
Cask Number 95010	9000121	8	**************************************
	Date	119195	Andrew Control of the
		<del></del>	

CHAPEL HILL THERED OF DURHAM HERALD EDITION
DURHAM, N. C.

Renad

N4C-0147 AB/C

DEC - 9 1994

OCT 24 94

# Fire hits another dorm lounge Weekend blazes prompt UNC officials to request SBI help

By RAY GRONBERG

The Chapel Hill Herald

CHAPEL HILL — A pair of weekend dormitory fires have prompted UNC officials to call for help from the State Bureau of Investigation.

Both fires occurred Saturday, but the call to the SBI didn't go out until after a 4 p.m. incident at Morrison dorm, UNC police Capt. W.L. Dunn said.

A smoldering newspaper left on a couch caused about \$100 worth of damage in the building's third-floor TV lounge, according to a statement from Chapel Hill Fire Department Capt. Bill Minton.

The Morrison incident followed an early-morning lounge fire at nearby Ehringhaus dorm that caused about \$25,000 in damage and forced students to evacuate for more than three hours.

It was the second fire at Ehringhaus this month.

UNC officials say they're concerned. "The first two [at Ehringhaus] appeared to be accidental, but the third one [at Morrison] appears suspicious," said Wayne Kuncl, UNC's director of housing. "When you see evidence of a burning newspaper on top of a cushion, you start to wonder."

Chapel Hill fire marshals and the UNC police are leading the investigation of Saturday's fires, according to a statement from UNC officials.

But Sunday afternoon provided yet another incident.

Chapel Hill firefighters were called to Hinton James dorm at about 4:35 p.m. when a toaster oven in a fifth-floor resident assistant's room started to smoke.

Preliminary indications were that no fire broke out, even though about 150 students had to evacuate for roughly 45 minutes while firefighters and UNC police checked out the situation.

What they found, firefighters said, was a malfunctioning appliance. The toaster oven's switch was off, but its coil was on and red-hot. The resident assistant living in the room had been gone for most of the day.

9501090001218

Page 18/2

please see FIDEEA

FROM 1

Investigators attributed the Lewis the recent alarms "are Ehringhaus fires — the first occurring Oct. 9 in the sixthfloor lounge, the second at about 3 a.m. Saturday in the fifth-floor lounge — to carelessness and unattended cigarettes. 📜 🔅 🐪 🐪

But UNC police responding to the Morrison fire found a half-burned and folded newspaper section lying on a couch. Kuncl said they also found two slightly charred bulletin board fliers on the floor of the nearby lobby.

Word \_\_\_ and worry about the incidents at Morrison and Ehringhaus appear to have spread-among-students and their parents.

Chapel Hill Assistant Fire Chief David Lewis, who supervised firefighters at Hinton James Sunday, said he fielded calls "from about half the state" over the weekend. "Forty-seven irate parents, all thinking their children are in danger."

Residents aren't immune. Hinton James resident as-Hinton James resident as stepped up foot patrols inside sistant Gillian Steinberg told the dorms.

scaring people" while she waited on firefighters to give the all-clear signal Sunday.

Steinberg backed off that statement, however, when questioned further. "It's an annoyance more than anything else," she said.

University officials said in a statement Sunday that they've told residence hall staff members throughout the campus about the incidents at Morrison and Ehringhaus. They said they've also instructed hall staff to be alert for any suspicious activity.

Little word, however, seemed to have trickled down to the Hinton James staff by Sunday afternoon.

"All we've been told is that the lounges have been closed by someone higher than us," said resident assistant Robert Simes. "Nothing's been handed down yet."

Simes and Steinberg reported, however, that they've noticed that UNC police have

Page 2012